


GAS SAFETY RECALL

Updated on 28 October 2022 to confirm affected cookers and information about inspection and repairs.

PRA 2022/19498 – Swift Appliance Group 500 Series Cooker/Grill and Cooktops

Model Numbers 502BHSP, 502BHFV, 502DHSP, 502RHSP, 502SHFW, 502SHW, 502WBHSP, 503BHSPM, 503BHSP, 503BHSPMLG, 503BHSW, 503DHSP, 503RHSP, 503SHSPM, 503SHSW and 503BHSPN. Approval Number AGA 6488G



Identification: To identify affected appliances, check the model number on the data plate. Open the glass lid and look for the data plate on the inside front left side of the lid.

Products were supplied to caravan, camper, motorhome manufacturers and directly to consumers.

Cookers manufactured:

- **between 1 January 2019 and 31 May 2020** (inclusive) have been recalled – Follow instructions under **action required** below.
- **before 1 January 2019** are not subject to recall – consumers can continue to use these cookers as per the instructions for use provided with the appliance.
- **on or after 1 June 2020** are not subject to recall – consumers can continue to use these cookers as per the instructions for use provided with the appliance.

Defect: A part of the gas supply pipe in the front left burner may break or develop a hole. This can cause the gas to leak.

Hazard: If the gas leaks in the presence of an ignition source this can lead to an explosion and/or fire, which may result in serious illness, injury or death. The defect has caused incidents that have caused serious injuries and burns.

Action required: For cookers manufactured **between 1 January 2019 and 31 May 2020 (inclusive):**

1. Turn the front left burner control knob to the off position, remove the knob and store it out of reach of other users.
2. **DO NOT USE** the front hotplate left burner. The other burners and the electric hotplate can be used.
3. Contact a Swift service agent to arrange an inspection and repairs (if required). Swift service agents information is available here: <https://swiftappliancegroup.com.au/repairs-warranty/>

If you are in a remote area or unable to access an approved Swift service agent, contact a licensed plumber or gasfitter and request they contact Swift for authorisation and instructions on how to conduct the remedial process.

Contact details for Swift Appliance Group:

- swiftrecall@outlook.com
- **0412 821 912** (Monday to Thursday 8am to 4:30pm and Friday 8am to 1:30pm)
- Register your details and receive updates: <https://swiftappliancegroup.com.au/gas-cooker-recall-register/>

It is recommended that consumers install a gas leak detector inside the cupboard underneath the gas cooker unit if the caravan or motorhome is intended to travel off-road.

See www.productsafety.gov.au for Australian product recall information